

# How to Build a CNC Machine

# Building a CNC Machine

- 1** Safety
- 2** Hardware
- 3** Electronics
- 4** Software
- 5** Resources

**Safety**

**Your CNC will  
move on its  
own and try  
to kill you.**



# Safety

- **NOT A JOKE. WE ARE TALKING ABOUT VERY DANGEROUS MACHINES.** Wear ear and eye protection
- You need to think about escape routes, Emergency Stop, Limit Switches, How you will call 911.
- Test cuts in the air with the spindle OFF.
- **MAKE A CHECK LIST AND FOLLOW IT BEFORE YOU HIT GO.**
- Don't leave it alone. You will be tempted to...

# Why use a CNC?

- Very similar to the transition between using a typewriter and a computer.
- Accurate
- Repeatable
- Fast
- It can work while you do other things.
- You can try something, tweak it, and cut it again. Like reprinting a single page of a document.
- Can work with larger bits
- Can work with extremely small bits
- Convenient when you have multiple items to make
- But, it has its place. Often still use a table saw, chop saw, planer, etc.



# Furniture





SketchChair



# ART



# PCBs



# Components of a Design




# Pens, Jewelry



# Build vs Buy

- **Lots of options. More coming every week.**
- **Small light machines:**
  - ShapeOKO (Carbide3d.com)
  - X-Carve (Inventables.com)
  - Search: 3018 Desktop CNC
- **Heavier Machines:**
  - CNCRouterParts.com,
  - tormach.com,
  - many others.
- **EBay, banggood.com**
- **Auction web sites.**


Often inexpensive big machines BUT, may need 3 phase power, etc. Can be complicated to program, calibrate, etc.
- **Convert an existing machine**



**Hardware**

**Rigidity is KEY**

Aluminum frame. 8020 framework.



# Linear Movement



Rails



Bearings



MakerSlide




Angle Iron

# Making Things Move

Consider Backlash



Acme Thread



Ball Screws




Belt and Pulley




Rack and Pinion

# Electronics

# CNC Electronics



# Stepper Motors



TB6600 5A Driver




- Nema 17, Nema 23, Nema 34
- Ratings: Oz-Inch 100, 300, 500, 1000!
- Power supply - 24-48V 10-30A
- Stepper motor drivers
- Step and direction
- Use latching connectors and 18/4 stranded wire for Nema 23

# Control Hardware



- Smooth stepper - Connects to PC via USB or Ethernet
- Planet CNC or similar control computer
- Arduino-based controller. GRBL Some have built-in motor drivers, wifi, ethernet, usb, etc.

# Control PC



- Parallel Port vs USB vs Ethernet
- Use an older version of Windows - Windows 7 - though Win7 obsolete soon.
- Get all s/w off the PC
- Turn off auto-everything and every background task.

# Miscellaneous stuff



Relay outputs - 2 is good for controlling other equipment, spindle motors, lasers, etc. Easy to control from G-Code



Limit switches - mechanical vs hall effect.



E-Stop is essential. It will save you, your workpiece or your bit one day.



Power supply - Switching vs Analog. Use latching connectors. Don't skimp


# Spindle



- Simple: Use a small Dewalt Router or Bosch Colt. Mounts available.
- Air/water cooled spindle - many available on eBay. Think about collet size. Order spare collets. Don't skimp. ER11 collets ok for 1/4" bits. ER20 good for 1/2" bit. ER32 good for a mill.
- 3 Phase Inverter Hitachi vs others - lots of instructions on setting these up. Need to set about 5-10 parameters - but set as few as possible! Speed control via computer - Can be done through a digital or analog connection.


**Software**

# Control Software



- Mach3
- Mach4
- LinuxCNC
- PlanetCNC
- GRBL Sender


# Flow of operations



# CAD - Design Software


Good idea to learn more than one.

- Solidworks
- Fusion 360
- Sketchup
- Rhino3D
- TinkerCAD.com
- Vectric V-Carve Pro
- OnShape.com
- libreCAD.com
- vectary.com
- OpenSCAD




# CNC Lathes

# Machine Axis



Mill



Lathe

# How to Make Round Things



**Extra Stuff**

# What Goes Wrong?


- Parts come loose. Fly across the room or jam up the cutter - break the bit.
- Forget to power on the inverter or similar.
- Wrong speed of cut
- Forget to follow checklist. (MAKE A CHECKLIST!)
- Stepper misses steps. Can be mechanical issue or electrical (bad connector or noise)
- Something comes loose. Locktite!
- Mechanical Failure - motor couplers
- Don't stand in the path of cutters/parts that might fly

# Resources

- <https://loen.design> (lists of suppliers & software)
- [Vectric.com](https://www.vectric.com) forums (fantastic resource)
- [CNCCookbook.com](https://www.cnccookbook.com) (excellent blog of all things CNC)
- **YouTube**
  - Frank Howarth - makes good use of a CNC as just another tool in the shop
  - This Old Tony - excellent CNC resources
  - NYC CNC - Lots of Fusion 360 examples
  - Lars Christensen - Fusion 360 expert
  - CNCNutz - very good explanations of CNC details



# Thanks!




**Rich Loen**

rich@loen.design

www.loen.design

instagram.com/loen.design

youtube.com/richloen



**Chris Manning**

@silver\_hand most everywhere.

Offhours.show